Migrate PSDS to OPM

Tanja Brusen
CAD Specialist
Vattenfall A/S Heat Nordic
Denmark

Preparing

- Installation
- Find files/db – place them in current Dataset
  - Ams.lib
  - Ams_user.lib
  - Pltspace.mdb or SQL
  - Rimref.dat
- Set the connection to mdb in the .pcf-file
- Select data source

Installation Server

- Server
  - PW Integration Server
  - PW Orchestration framework
  - PW Automation Service
  - PW Administrator
  - OPM Server
  - OPM Administrator
    - Client software (to run test Migration on Server):
    - PW Explore
    - OPM

Installation Client

- Client
  - PW Explore
  - PW Administrator
  - PW Automation Service
  - OPM
  - OPM Administrator

Testing the first Model Conversion

- Clean up a PSDS.dgn file (NOT in OPM)
- Then open file in OPM. First time, select source
- Run Upgrade and Convert



VATTENFALL

What's happening



Configure Mapping





VATTENFALL

Schema

- OpenPlant_3D.01.04.ecschema.xml
- Supplement scheme: BentleyBase.01.00.ecschema.xml, OpenPlant_3D_Supplemental_Mapping_PSDS.01.04.ecschema.xml



VATTENFALL

Succes?

- Check object into OPMS
- Run an iso
- Job done!